Map ID MAP FINDINGS

Direction Distance

Distance EDR ID Number
Elevation Site EDR ID Number
EDR ID Number

EZ768 MANHOLE 59506 NY Spills S104284063
North VAN SICKLEN ST/GRAVES END N/A

> 1 BROOKLYN, NY

1.072 mi.

5658 ft. Site 1 of 2 in cluster EZ

Relative: SPILLS:
Higher Name: MANHOLE 59506

Actual: Address: VAN SICKLEN ST/GRAVES END

 18 ft.
 City,State,Zip:
 BROOKLYN, NY

 Spill Number/Closed Date:
 9909943 / 2002-03-29

9909943 Facility ID: Facility Type: ER DER Facility ID: 163310 Site ID: 196027 DEC Region: 2 Spill Cause: Unknown Spill Class: C4 2401 SWIS: Spill Date: 1999-11-16 Investigator: **JHOCONNE** Referred To: Not reported Reported to Dept: 1999-11-16 CID: 389 Water Affected: Not reported

Spill Source: Unknown Spill Notifier: Other Cleanup Ceased: Not reported Cleanup Meets Std: False Last Inspection: Not reported Recommended Penalty: False **UST Trust:** False Remediation Phase: 0

Date Entered In Computer: 1999-11-16
Spill Record Last Update: 2002-03-29
Spiller Name: UNKNOWN
Spiller Company: Unknown
Spiller Address: UNKNOWN
Spiller Company: 999
Contact Name: CALLER

DEC Memo: "Prior to Sept, 2004 data translation this spill Lead\_DEC Field was

O'CONNELL "

Remarks: "CALLER REPORTING A SPILL OF HALF 1/2 PT OF MATERIAL ON 200 GAL OF

WATER CONTAINED IN HOLE CONED#129014 CLEAN UP PENDING LAB RESULTS NO

CALLBACK NECESSARY"

All Materials:

 Site ID:
 196027

 Operable Unit ID:
 1088637

 Operable Unit:
 01

 Material ID:
 299004

 Material Code:
 0066A

Material Name: unknown petroleum
Case No.: Not reported
Material FA: Petroleum
Quantity: 1.00
Units: G
Recovered: .00

Oxygenate: Not reported